

CITY-COUNTY HEALTH DEPARTMENT
 Colorado Springs, Colorado

B# 208 P

Approval: VA & FHA
 Yes No

7422303001
 Sewage Disposal Inspection Form


Date of Ins: JUNE 13, 1967
 Sanitarian Ray No. EDSTROM

Location (Street Number) 1404 Gold Camp Road occupant John Wepping
 Legal Description S.W. CORNER, Gold Camp Rd. & Talc Lane, Lot 7, B1K B
 Contractor Owner Plumber Don Carlson
 Type Construction Frame + Brick Grade House Sewer
 No. of Bedrooms ?
 Primary Treatment: (septic Tank)
 Type of material El Paso Con. Approved No. Compartments
 Width Length Depth (eff.)
 Depth (Total) Liquid capacity 1750 Gallons

Secondary Treatment:
 Leaching Pits (No.) 1 soil See Perc Test Perc Test Attached
 Lining Material Cement Block Capacity in Gallons over 3,500 ✓
 Diam. 11' Depth 9'4"

Disposal Field Soil Perc. Test
 Total length of tile lines Number of lines
 Distance between lines Length of each line Absorp. Area
 Type of Tile Trench Depth Trench Width Grade
 Type Filter Material Depth: Under Tile Over tile

Cesspool:
 Lining Material Soil
 Diam. Depth (effl.) Cap.



[Handwritten signature]

Ref

CITY-COUNTY HEALTH DEPARTMENT

Colorado Springs Colorado El Paso County

No 208

PERMIT

Individual Sewage Disposal System (Construction, Alteration or Repair)

Issued To John Wierking Date April 4, 1967

Address of Property SW corner, Gold camp road & Talc Lane, Lot 7, Blk B
1404 Gold Camp Rd. (Permit valid at this address only)

Builder - Contractor - Owner—Address same Phone _____

Sewage-Disposal System work to be performed by Carlson Phone _____

This Permit is issued in accordance with Regulation XII and Article 2 of Chapter 66, Colorado Revised Statutes 1963, as amended by the addition of a new Section 66-2-16. (H.B. 1205, 7-1-65). PERMIT EXPIRES upon completion —installation of sewage-disposal system or at the end of six (6) months from date of issue—whichever occurs first— (unless work is in progress).

3357

Oct. 4, 1967
(Date of Expiration)

[Signature]
Director, City-County Health Dept.

Permit Fee \$ 5.00
Mileage (8c/mile to and from site) 10 .80
Total Fee 5.80

NOTE: Leave entire sewage-disposal system uncovered for final inspection.

24-hour advance notice required.

Septic tank 1000 gals. Field _____ feet of trench _____ inches wide.

Seepage bed _____ ft. long _____ ft. wide. Seepage pit 3000 gallons.

The Health Officer shall assume no responsibility in case of failure or inadequacy of a sewage-disposal system, beyond consulting in good faith with the property owner or representative.

1404 Gold Camp Rd

E

7422303001

6-13-67

SOIL PERCOLATION TESTS FIELD DATA SHEET

Nerschel K. Nichol

CLIENT ^{IE} John Weipking 813 Orion

TEST NO. 9118

TEST LOCATION SW corner ¹⁴⁰⁴ Gold Camp Road & Talc Lane, Lot 7, Block B

DATE 3-22-67

TRIAL NO.	DEPTH START, IN	START TIME	DEPTH FINISH, IN	FINISH TIME	TOTAL DROP INCHES	TOTAL DROP TIME, MIN.	MINUTES TO DROP 1 INCH
1	27	1333	39	1336	12	3	.33
2							
3							
4							
5							

SOIL LOG

FROM	TO	SOIL CLASSIFICATION	MOISTURE
0'	10'	DG	

FHA-1103-7.3 ^{From Larry Summer} FHA-1103-8.5
 LEACHING FIELD SEEPAGE PIT
 REQUIRED AREA OF TRENCH BOTTOM REQUIRED SIDEWALL AREA
 PER BEDROOM 85 SQ. FT. PER BEDROOM SQ. FT.

REMARKS: Extremely coarse DG. Saturation impossible.

1000-gal - disposed in well = 3000 gal

DATE HOLE SATURATED 3-21-67 TIME 1:33


DATE PERCOLATION TEST MADE 3-21-67 TIME 1:36

RLB
OBSERVER

Nerschel K. Nichol
PROFESSIONAL ENGINEER

LINCOLN DeVORE TESTING LABORATORY
Colorado Springs, Colorado


"SUNRISE PARK"



S.I.P. = Set Iron Pipe Monument

I hereby certify that on October 13, 1966 a survey was accomplished under my supervision of Lot 7, Block B, Sunrise Park, a subdivision in El Paso County, Colorado. Iron pipe monuments were set at the corners of the tract as shown hereon, and are correct to the best of my knowledge and belief.

Gerald D. Harris
 Gerald D. Harris



GEORGE L. WILLIAMS
 CONSULTING ENGINEER
 321 1/2 S. TEJON
 COLORADO SPRINGS, COLO.

